


PROCESS FLOW CHART



QC-1 Incoming inspection for mill visual defect and comparing with mill certificate for chemical composition.

QC-2 In process inspection for visual defect, thickness width etc.

QC-3 Final inspection for mechanical properties, dimension and tolerances or another test required by customer.

QC-4 Additional final inspection.

